

TRUCK REMARKETING SERVICES

SPECIFICATION SHEET

Fleet Name <u>HFC Leasing</u>		Unit # <u>1751</u>		VIN # (last 6) <u>823556</u>	
Location		Contact			
Address <u>317 Arlington Ave.</u>		Phone <u>615-324-3538</u>			
City <u>Nashville</u> State <u>TN</u>		Zip <u>37210</u>			
Year <u>2004</u> Make <u>Peterbilt</u>		Frame <u>Steel</u>		Aluminum Double	
Model <u>387</u>		Interior Type (Name) <u>Custom</u>			
Full VIN # <u>1XP70B9X-2-40823556</u>		Interior Level		Low <u>Mid</u> High	
Engine Make <u>CAT</u> Model <u>C-15</u>		Interior Upholstery		Vinyl <u>Cloth</u> Button-Tuck	
HP (rated) <u>435</u> HP (ECU) <u>435</u>		Seat Suspension		None LH Air <u>Dual Air</u>	
Sleeper None Box-Flat Box-Mid Box-Raised		Fuel Tanks		Steel <u>Aluminum</u>	
Integral-Flat Integral-Mid <u>Integral-Raised</u>		Capacity Tank 1		<u>150</u> Tank 2 <u>150</u> Tank 3	
Sleeper size <u>63"</u>		Bumper <u>Aero</u>		Chrome Steel/Alum	
Wheel Base <u>236"</u>		Interior Color <u>Gray</u>			
Odometer <u>449594</u> ECU <u>451516</u>		Paint Color <u>White</u>			
Transmission Make <u>Eaton Fuller</u>		Exhaust <u>Single</u>		Dual <u>Vertical</u> Horizontal	
Model <u>RTO16910V-DM</u> Speeds <u>10</u>		Front Wheels <u>Aluminum</u>		Steel Spoke	
Type Manual <u>Automatic</u> Auto-Shift		Radio <u>AM/FM</u>		<u>Cassette</u> CD <u>Weather Band</u>	
Suspension <u>Air-Ride</u> Spring Heavy		PTO Yes <u>No</u>			
Front Axle Make <u>Mentor</u> Capacity <u>12000</u>		Mirrors <u>Heated</u>		RH Power <u>Dual Power</u>	
Front Axle Position Set-Forward <u>Set-Back</u>		Wet Line Kit Yes <u>No</u>			
Rear Axle Make <u>Spirer</u> Capacity <u>40000</u>		Rear Wheels Aluminum <u>Steel</u>		Alum Outside Spoke	
Type Single <u>Tandem</u> Ratio <u>3.55</u>		Brakes <u>ABS</u> <u>Air</u>		Hydraulic <u>Drum</u> Disc	
3rd Axle <u>None</u> Pusher Tag Lifiable		New Paint Yes <u>No</u>			
Power Steering <u>Yes</u> No		Dual Beds <u>Yes</u> No			
Engine Brake None <u>Jake</u> Driveline Exhaust		Steer Axle Brakes		<u>70%</u> <u>70%</u>	
Air Conditioning <u>Yes</u> No		Drive Axle Brakes		<u>90%</u> <u>90%</u>	
Fuel Type Gas <u>Diesel</u>				<u>90%</u> <u>90%</u>	
Chassis Fairings None Partial <u>Full</u>		3rd Axle Brakes (if applicable)		% %	
Roof Fairing Yes <u>No</u> Side Extenders <u>Yes</u> No		Brake Backing Plates (Dust Shields)		Yes <u>No</u>	
Cab Type Cabover <u>Conventional</u>		Engine Serial # <u>MBN 23252</u>			
Body Type <u>Tractor</u> Truck Cab & Chassis		Engine CPL / Arrange. # <u>2404265</u>			
Exterior Visor None <u>Fiberglass</u> Aluminum/Stainless		Engine Hours <u>12341</u>			
5th Wheel None Stationary Manual <u>Air</u>		Wheel Mounting Stud-Pilot <u>Hub-Pilot</u>		Spoke	
Tire Size Front <u>295/75 R 22.5</u>		<p><b>Brake Legend</b></p> <p>BD = Bad Drum CL = Cracked or Separated Lining LS = Leaking Seal</p> <p><b>Tire Legend</b></p> <p>C = Cut D = Dry Rot F = Flat M = Mismatched Tread or Casing</p> <p>MA = Mismatched Axles (front vs. rear)</p> <p>R = Recap V = Virgin W = Irregular Wear X = Capped More Than Once</p> <p><b>Tread Legend</b></p> <p>H = Highway L = Lug</p>			
Rear <u>295/75 R 22.5</u>					
H 18/32		H 18/32			
L 15/32 L 15/32 L 15/32 L 15/32					
L 15/32 L 15/32 L 15/32 L 15/32					
132 132 132 132					

Inspector J. K...

Date 6-1-07

**CONDITION REPORT**

VIN # (last 6) 823556

ENGINE COMPARTMENT		PIC #	ESTIMATE
<input checked="" type="checkbox"/>	Engine oil - Condition & Level		15
	Low of oil		
<input checked="" type="checkbox"/>	Coolant - Level & Condition		
<input checked="" type="checkbox"/>	Record coolant protection level		
	-45°		
<input checked="" type="checkbox"/>	Radiator, reservoir, hoses		
<input checked="" type="checkbox"/>	Fan hub / clutch, blade, shroud		
<input checked="" type="checkbox"/>	Air intake - manifold, air-to-air & piping		
<input checked="" type="checkbox"/>	Belt alignment, condition & adjustment		
<input checked="" type="checkbox"/>	A/C compressor, clutch & brackets		
<input checked="" type="checkbox"/>	Engine oil & fuel leaks		
	STEAM cleaned		
<input checked="" type="checkbox"/>	Steering gear, draglink, pump & hoses		
<input checked="" type="checkbox"/>	Air compressor, governor & hoses		
<input checked="" type="checkbox"/>	Exhaust system - manifold, turbo & piping		
<input checked="" type="checkbox"/>	Starter & solenoid		
<input checked="" type="checkbox"/>	Charging system - Record voltage		
	13.7		
INSIDE CAB AND SLEEPER		PIC #	ESTIMATE
<input checked="" type="checkbox"/>	Start engine - Listen for unusual noises		
<input checked="" type="checkbox"/>	Clutch & clutch brake adjustment		
<input checked="" type="checkbox"/>	Steering wheel, tilt column, shafts & u-joints		
<input checked="" type="checkbox"/>	Glass - windshields, doors & mirrors		
<input checked="" type="checkbox"/>	Windshield wipers & washers		25
	Left w/washer Inop		
<input checked="" type="checkbox"/>	Mirrors - heat & power operation & condition		
<input checked="" type="checkbox"/>	Door hinges, latches, regulators & knobs		
<input checked="" type="checkbox"/>	Seats - air operation & condition		
<input checked="" type="checkbox"/>	Seat belts & bunk restraints		
<input checked="" type="checkbox"/>	Upholstery, carpet, mats, etc....		
<input checked="" type="checkbox"/>	Sleeper / cab privacy curtains & tracks		
<input checked="" type="checkbox"/>	Cabinets, doors & hinges		
<input checked="" type="checkbox"/>	Dash, gauges, switches & interior lights	23	50
	Air Dump DASH Light out		
<input checked="" type="checkbox"/>	Engine monitor display & LCD readout		
<input checked="" type="checkbox"/>	Engine brake		
<input checked="" type="checkbox"/>	Radio & speakers		
<input checked="" type="checkbox"/>	Horns - city & air		
<input checked="" type="checkbox"/>	Parking brake		
<input checked="" type="checkbox"/>	Air pressure build up - Governed psi		
	135		
<input checked="" type="checkbox"/>	Air leaks - dash, foot valve, shift knob, etc....		
<input checked="" type="checkbox"/>	HVAC system, fans, control panels & vents		

CONDITION REPORT

VIN # (last 6) 823556

UNDER VEHICLE		PIC #	ESTIMATE
<input checked="" type="checkbox"/>	Front axle, king pins, tie rod & ends		
<input checked="" type="checkbox"/>	Engine & transmission mounts		
<input checked="" type="checkbox"/>	Frame & crossmembers		
<input checked="" type="checkbox"/>	Air leaks on outside of truck		
<input checked="" type="checkbox"/>	Drain wet tank - oil in air system?		
<input checked="" type="checkbox"/>	Air dryer		
<input checked="" type="checkbox"/>	Hydraulic brake lines & components		
<input checked="" type="checkbox"/>	Brake hoses - cracking & chafing		
<input checked="" type="checkbox"/>	Brake drums & linings		
<input checked="" type="checkbox"/>	Wheel seals - leaks, etc...		
<input checked="" type="checkbox"/>	Driveshafts, u-joints, yokes, carrier bearing		
<input checked="" type="checkbox"/>	Transmission & rear axle - condition & leaks		
<input checked="" type="checkbox"/>	Rear axle & suspension alignment		
<input checked="" type="checkbox"/>	Suspension - springs, pins, hangers, etc...	72	600
<input checked="" type="checkbox"/>	Shocks, bushings & mount brackets		
<p>Bottom bushing out of Left FRT Shock All 6 Shocks leaking oil</p>			
OUTSIDE OF TRUCK		PIC #	ESTIMATE
<input checked="" type="checkbox"/>	Mufflers, stanchion mounts, guards		
<input checked="" type="checkbox"/>	Cab / sleeper air ride & mounting	21	200
<input checked="" type="checkbox"/>	Mirrors & mounting brackets		
<input checked="" type="checkbox"/>	Lights & reflectors		
<input checked="" type="checkbox"/>	Trailer cord, air lines, glad-hands, hangers		
<input checked="" type="checkbox"/>	Tires & wheels		
<input checked="" type="checkbox"/>	Fuel tanks & mounting		
<input checked="" type="checkbox"/>	Batteries, cables & terminals		
<input checked="" type="checkbox"/>	5th wheel - plate, bushings, cylinder, etc...		
<input checked="" type="checkbox"/>	Mud flaps, 1/4 fenders, brackets		
PAINT CONDITION & PHYSICAL DAMAGE		PIC #	ESTIMATE
<input checked="" type="checkbox"/>	Chrome Peeling on Grille	15	600
<input checked="" type="checkbox"/>	Hood cracked Rt side on Inside by Gullie	16	350
<input checked="" type="checkbox"/>	Paint off Rt mirror Bracket	17	50
<input checked="" type="checkbox"/>	Left mirror Cover scratched	18	100
<input checked="" type="checkbox"/>	Check Hood noise when opening hood, Diagnostics & Repair		100
<input checked="" type="checkbox"/>	Left & Rt Door Steps bent at Bottom	19	200
<input checked="" type="checkbox"/>	Paint scratched Left FRT wheel Fairing	24	100
Total Recon Estimate (include supplement sheet total if applicable)			\$ 2390
Supplement Damage Sheet Attached:		Yes	<input checked="" type="radio"/> No